



**MOUNTING INSTRUCTIONS**  
**For 45-1222H/45-1222RBH**  
**GL 1800 FRONT FAIRING HALO**  
**2001-2008**

NOTE: Read instructions thoroughly before installing. Drilling required.

1. Place bike on center stand.
2. Remove the windshield panel in accordance with manual directions.
3. Remove the front fairing garnish by removing the setting bolt at the top and setting screws on the bottom. Photo 1 and 2.
4. Center the light halo on to the front fairing garnish as shown in photo 3. Mark drill positions on fairing garnish. Drill the front fairing garnish where marked with a #48 drill. Attach fairing halo with 2 screws provided.
5.
  - a. Reattach front fairing garnish with halo. Photo 4.
  - b. Turn front wheel to ensure halo clears fork assembly.
  - c. Carefully align the adhesive pads so the ends of halo can be secured with the 2 wire ties to the rear inside fairing. Clean the area before the adhesive pads are put in place. Photo 5.
6. Wire into running lights. Attach the green wire to the positive and the black wire to the ground.



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Complete